



TUFF TEMP CORPORATION

– *HEAT RESISTANT TEXTILES AND BELTING* –

928 Jaymor Road Suite C-150 • Southampton, PA 18966

Phone: (215) 322-9670 • www.tufftemp.com • Fax: (215) 322-3905

Directions On How To Use Wear Gard Solution

1. Pour some of the Wear Gard solution into small container and add water to it. The amount of water should equal about 10% of the amount of Wear Gard that you are using.
2. Mix diluted Wear Gard solution with a regular 1" wide paintbrush. Use a new brush each time as the Wear Gard is difficult to wash out of the brush if it sits around for a while and hardens.
3. Apply a thin coating with the brush.
4. Drying time if it sits on its own is about an hour or two. If you use a hair dryer or heat gun, drying time can be about 20 – 30 minutes.

Note: The Wear Gard solution is not harmful. However, gloves should be worn when applying.

WEAR GARD TREATING THE BELT LACING:

1. Square belt off on both ends after desired length is established.
2. Paint a 1" wide coating of Wear Gard on both ends of the belt, and on both sides of the belt ends.
3. Then let belt dry for about 30 minutes or until almost dry.
4. Apply clips to belt while belt is still damp.
5. Let belt completely dry before installing. Dry time if it air dries is about 1 – 1 ½ hours. However, if you use a heat gun or even a hair dryer on the belt ends it can dry faster. Note, if belt is installed while Wear Gard is still damp, the lacing will not have optimal strength. However, once Wear Gard fully hardens the lacing join is very strong and it should not pull out.